


## USB Vibration Measuring System

### Features

- Vibration measurement and analysis are possible just by directly connecting to PC.
- Small and light best for carry out.




### System configuration



### Specifications

Item	Specifications
Data Output	3-axis real time graph displays
Data Preservation	Preservation with a CSV form
Sampling Frequency	60Hz ~ 300Hz
A/D Conversion	10bit
PC System Requirements	Windows 98, Me, 2000, XP
Interface	USB (Sensor side be Mini USB)
Dimension	50 x 50 x 20 (mm)



Operation example by analysis software